
	Approved For Release 2005/08/03 : CIA-R35780-00810A001500650003-1	
and the state of t	ACBIECOTRING SCIENCE.	25X
· · · · · · ·	CLASSIFIC? (RIP	energy (
COLUMN	octor 870/8014	more at the second seco
TOPIC	25.8.1	25X
SEC. SERVICEMENTS LESS SET SETTINGS OF SECURITY OF SEC	PLACE OBTAINED.	with the second
EVALUATION.	25X1	with chall California
DATE OF CON	DATE PREI RED 5 May 1953	vicani/yvyville allocid () 5
DATE OBTAIN	EDDAIE PREI PREI PREI PREI PREI PREI PREI PR	C. Saltzani, Marketa II. a
DECERENCES	The chartes on Attach	pp game so to the first
MELENCE	ENCLOSURES (No. 8: TYPE) 2 - the sheet has an Affin	a particular and the second
PAGES		
REMARKS_		
and the process of the organization to the other way in which the	THE REPORT OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS	ggan Ar rich has sample and rich
E Voppmannennennennennen skriver	THE CONTROL OF THE PARTY OF THE	unit: Buffalts (C. 2019), A. C. 2777
5X1	The state of the s	
	Air activity observed at Stanken arfield from through library 1953	
25X1	included:	
	March. From 10 a.m. to noon, three Li-2s made that training frights at extended landing gears. The flights lasted for a put 15 minutes. Some planes extended landing gears the field in the afternoon.	
	Limber Will observed.	
	10.20 m indiana	
	11 March. From 10 a.m. to 12:30 p.m. individual	
5X1	700 JANGING COM 140 2 18K-140	
3 / 1	the hangars.	
	the hangers. 13 March. In the morning, Li-2s rade local training "lights with retracted landing gears. No air activity was observed in the a termoon in cloudy landing gears. No air activity was observed in the a termoon in cloudy	
	weather.	
	14 March. In the morning, 11-2: made local ar , is fair. duration at 20 minutes interval The weather, is fair.	
= -	16 March. At 2:10 p.m., a Li-2 anded at the field.	•
	16 March. At 2:10 p.m., t	25X1
	16 March. In the morning, Li-2s made local the ming fli late	
5X1	18 March. Air activity was conducted as on the preceding day. The weather was fair. A plane, apparently a Pe-2, took of at 10 a.m. A plane of the was fair. A plane, apparently a plane, after a percent of the af a soon.	
	was fair. A plane, apparently a ree-2, took of was fair. A plane, apparently a ree-2, took of same tipe was repeatedly seem a oft in the af a room. 19 March. No air activity was beenved from 1 to 11 h.m. four 1d-2s and 19 March. No air activity was beenved from 1 to 11 h.m. four 1d-2s and 19 March. No air activity was beenved from 1 to 12	
	2 Yak-14s were parked in front of the name of the was also seen.	
**		. A section of the se
	CLASSIFICATION SECRET	
Market on the state of the stat	** The state of th	5
		~ 3

SECRET

25X1 21 March. No air activity was observed in fair weather. 22 March. At 6:30 p.m., a Li-2 landed at the field. 23 and 24 March. From 10 a.m. to 7:30 p.m., no eir activity was observed in spite of fair weather. 25 March. One Li-2 each took off at 1:50 and 5:50 p.m., and a Li-2 landed at 6 p.m. 26 March. In the morning, only one Li-2 was observed landing. From 3:30 to 7:25 p.m., individual Li-2s flew some circles over the field. Four Li-2s and three Yak-Lies were parked in front of the 28 Merch. A Li-2 landed between moon and 1 p.m. Weather was 8/10 overcast. 29 March. No air activity was observed except for a Li-2 which took off at 11:30 a.m. Weather was overcast. 30 March. At 11 a.m., a la-2 took off for a local training flight which was extended until about 3 p.m. except for one intermediate landing. Every fifteen minutes, the plane came in for a landing but · without extending its landing gear and without actually landing. The plane would come down as low as 10 maters above the ground. No aircraft were observed parked at the installation between 10 and 11 a.m. 25X1 2. On 19 March five fuel tanks in the size of railroad tank cars at the fuel dump in the morthern portion of the field. 25X1 they were scheduled to be dug in there. 25X1 On 11 March, the radio installation with four 25X1 masts had moved to another place. In the southern portion of the field an old fence was being replaced by a new one. 25X1 25X1 On 12 Merch, individual Ld-2s practiced flying at the field in fair weather. At 9:30 a.m., six Li-2s were observed parked in front of the hangars. After 8 p.m. On the afternoon of 19 25X1 noise of flying aircraft 25X1 25X1 25X1 2 Po-2s, and 5 single-engine planes at the field. Seven fuel tanks with an estimated capacity of 20,000 kiters each were being set up at the northern edge of the field. A pipe line extended 25X1 to the railroad line. In the afternoon of 13 March, no air activity was observed at the field except for a Yak-14, which landed at 2:20 p.m. Four Li-2s were parked in front of the hargers. Li-2s and Yek-14s made local training flights on 2 April. A Yak-14 which had taken off from the field was repeatedly 25X1 observed circling over Falkensee. 25X1 A Pe-2 and a Po-2 were also observed parked at the installation. SECRET

	SECRET	
		25X1
	3 • • • • • • • • • • • • • • • • • • •	
25X1	7. On 13 March two men bransloading fuel from a railroad tank car at the fuel dump near the northern edge of the installation. Four fuel containers connected to a ofpe system were also observed there. A manhole was observed beside one of the fuel tanks. On 2 April, five additional fuel tanks in the size of railroad tank cars were seen at the dump.	
	8. The airfield was surrounded by a wire lence. A board fence was available only adjacent to the main gate of the installation. A new fence was being erected parallel to the fence on the south side of the field.	
25X1	9. Radio installations observed at the field included two PRV-45 DF stations in the southwestern portion of the field and the western extension of the east-west runway; one inner low frequency beacon west of the runway; a spokes must on the roof of a building near the hangars and two antennas atop the flight control station.	
	10. About noon on 23 March, a single-engine and a short time later a twin-engine plane took off from the field. About .0 a.m., a single-engine plane was parked in front of the flight control station. A twin-engine plane took off at 5:30 p.m.	
25X1	a PKV-45 EF station n rth of the cemetery on Heer-Strasse, near a small transformer station. Two single-story temporary buildings and a radio tower 10 meters high were sees east of the road leading from north of the railroad line to Hellgow. About 250 meters east of the radio tower, there was a second radio station with four masts. The sabin in the middle of the installation was painted yellow.	
25X1	12, a fuel sump south of the railroad line.2	
25X1	1. Comment. Elements of an air transport regiment equipped with about 10 Li-2s are still stationed at Staaks a sirfield.	
25X1	2. Comment. It appears that the for er German underground fuel installetions in the northern portion of the field were being enlarged. For location of the dump, see Annex 1.	•
25X1	3. Comment. Paragraph 9 of the present report correctly lists all the radio installations available at the first.	25X1
25X1	See Annexes 1 and 2,	

SECRES



SECRET,


25X1
Annex 1 25X1

Legend:

- 1 Empty hangar
- 2 Low wooden building
- 3 Hangar with attached flight control station
- 4 Single-story permanent building
- 5 Hangar
- 6 Workshop or garage
- 7 Fuel dump
- 8 Garage
- 9 Garage
- 10 Parking site for tank trucks
- 11 Main gate
- lla Gate
- 12 Building with tower on top of which spokes antenna
- 13 Landing beacon C
- 14 An undetermined number of heavily damaged quartering buildings
- 15 Three quartering buildings
- 16 Destroyed factory
- 17 Fuel dump and temporary loam building with telephone line
- 18 Temporary loam building of undetermined purpose
- 19 Three low wooden buildings about three meters square with telephone line
- 20 and 21 PKV-45 DF stations
- 22 Villa
- 23 Target range, apparently unused
- 24 Fence

SECRET,

Inner Landing Beacon at taaken Airfield



SEURET 25X1